



Certificate of Registration

This certifies that the Quality Management System of

Energy Recovery Inc.

1717 Doolittle Drive
San Leandro, California, 94577, United States

has been assessed by NSF-ISR and found to be in conformance to the following standard(s):

ISO 9001:2015

Scope of Certification:

Design and Manufacture of Energy Recovery devices and equipment

A handwritten signature in blue ink, appearing to read 'SV'.

Sameer Vachani
Senior Director, NSF-ISR

Certificate Number:	C0217291-IS6
Certificate Decision Date:	13-OCT-2023
Certificate Issue Date:	13-OCT-2023
Cycle Effective Date:	16-OCT-2023
Certificate Expiration Date*:	15-OCT-2026

Issued by:
NSF International Strategic Registrations (NSF-ISR)
789 N. Dixboro Road, Ann Arbor, MI 48105 USA

Authorized Certification and/or Accreditation Marks. This certificate is property of NSF-ISR and must be returned upon request.

*Company is audited for conformance at regular intervals. To verify certification call (888) NSF-9000 or visit our web site at www.nsf-isr.org





Certificate of Registration

ANNEX PAGE FOR CERTIFICATE NUMBER: C0217291-IS6

This Annex is only Valid in connection with the above-mentioned certificate issued by NSF-ISR

CERTIFICATE ISSUE DATE:
13-OCT-2023

CERTIFICATE EXPIRATION DATE:
15-OCT-2026

Energy Recovery Inc.
1717 Doolittle Drive
San Leandro, California, 94577, United States

Location:

Energy Recovery Inc.- C0569834
2000 Chabot Court
Tracy, California, 95304, United States

Scope:

This location is part of site C0217291. Supporting processes include: Manufacture of Energy Recovery devices and equipment.

Location:

Energy Recovery Inc.- C0696503
25430 Clay Road,
Katy, Texas, 77493, United States

Scope:

This location is part of site C0217291. Supporting processes include: Support site operations for Headquarters.

Issued by:
NSF International Strategic Registrations (NSF-ISR)
789 N. Dixboro Road, Ann Arbor, MI 48105 USA

Authorized Certification and/or Accreditation Marks. This certificate is property of NSF-ISR and must be returned upon request.

*Company is audited for conformance at regular intervals. To verify certification call (888) NSF-9000 or visit our web site at www.nsf-isr.org

